

REFLEX PROTECT[®] TACTICAL

INSTRUCTIONS FOR USE OF REFLEX REMOVE

FOR SURFACES

1 Apply Reflex Remove generously to impacted surface.

2 Allow solution to rest for at least 30 seconds, to provide time for chemical process to break down the contaminates.

3 Blot or wipe dry.

4 Repeat as often as needed. Discard towels after use.

1

2

3

4



FOR PEOPLE

1 Apply Reflex Remove generously to impacted skin.

2 Dab or blot carefully with a clean cloth. **DO NOT RUB SKIN OR EYES!** (Contaminant may spread.)

3 Apply Reflex Remove liberally and use a new clean, absorbent cloth to blot area. Repeat as often as needed. Discard towels after use.

4 Use black light to engage UV Dye to determine if completely decontaminated - no UV light detection, no remaining Presidia Gel.

 **MADE IN USA**

Connect with Us @ReflexProtectTactical   